

DAMAGE AREA PT	DAMAGE AREA	SEVERITY DESCRIPTION PT	SEVERITY DESCRIPTION	MINI ECONOMY	COMPACT	FULL SIZE PREMIUM	INTERMEDIATE STANDARD	LUXURY	PASSENGER VAN	MEDIUM VAN	SMALL VAN	SPECIAL VAN	LARGE VAN
CHAPA MATRÍCULA TRS	Rear Number Plate	DISTORCIDO	Distorted	5,6	5,71	5,06	5,22	4,61	3,75	4,11	6,6	3,75	3,75
CHAPA MATRÍCULA TRS	Rear Number Plate	FALTA	Missing	5,6	5,71	5,06	5,22	4,61	3,75	4,11	6,6	3,75	3,75
CHAPA MATRÍCULA TRS	Rear Number Plate	PARTIDO	Broken	5,6	5,71	5,06	5,22	4,61	3,75	4,11	6,6	3,75	3,75
AILERON TRÁS	Tail-lift	DISTORCIDO	Distorted	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	FALTA	Missing	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	MOSSA >15cm	Dent >15 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	MOSSA >5-15cm	Dent >5-15 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	MOSSA 2-5cm	Dent 2-5 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	PARTIDO	Broken	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	RASPADO >5-15cm	Medium Scuffed >5-15cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	RASPADO 2-5cm	Light Scuffed 2-5cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	RISCO >15cm	Scratch >15 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	RISCO >5-15cm	Scratch >5-15 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AILERON TRÁS	Tail-lift	RISCO 2-5cm	Scratch 2-5 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AIR BAG CORTINA DTO	Right Curtain Airbag	FALTA	Missing	302,27	371,78	252,02	310,58	310,47	301,51	323,9	513,25	tb*	tb*
AIR BAG CORTINA DTO	Right Curtain Airbag	PARTIDO	Broken	302,27	371,78	252,02	310,58	310,47	301,51	323,9	513,25	tb*	tb*
AIR BAG CORTINA DTO	Left Curtain Airbag	FALTA	Missing	304,84	371,56	245,94	325,4	310,67	305,26	323,9	513,25	tb*	tb*
AIR BAG CORTINA DTO	Left Curtain Airbag	PARTIDO	Broken	304,84	371,56	245,94	325,4	310,67	305,26	323,9	513,25	tb*	tb*
AIR BAG CORTINA ESQ	Front Right Speaker	FALTA	Missing	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AIR BAG CORTINA ESQ	Front Right Speaker	PARTIDO	Broken	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ALFALANTE FTE DTO	Rear Right Speaker	FALTA	Missing	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ALFALANTE FTE DTO	Rear Right Speaker	PARTIDO	Broken	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ALFALANTE TRS DTO	Rear Right Speaker	FALTA	Missing	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ALFALANTE TRS DTO	Rear Right Speaker	PARTIDO	Broken	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ALFALANTE TRS ESQ	Rear Left Speaker	FALTA	Missing	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ALFALANTE TRS ESQ	Rear Left Speaker	PARTIDO	Broken	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
ANTENA	Antenna	DISTORCIDO	Distorted	21,28	47,4	141,69	122,28	138,87	tb*	14,37	20,94	73,97	154,31
ANTENA	Antenna	FALTA	Missing	21,28	47,4	141,69	122,28	138,87	tb*	14,37	20,94	73,97	154,31
ANTENA	Antenna	PARTIDO	Broken	21,28	47,4	141,69	122,28	138,87	tb*	14,37	20,94	73,97	154,31
AVENTAL DA FTE	Front Bumper Skirt	DISTORCIDO	Distorted	77,4	134,06	83,98	102,19	229,53	181,53	252,91	30,5	109,11	tb*
AVENTAL DA FTE	Front Bumper Skirt	FALTA	Missing	77,4	134,06	83,98	102,19	229,53	181,53	252,91	30,5	109,11	tb*
AVENTAL DA FTE	Front Bumper Skirt	MOSSA >15cm	Dent >15 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	MOSSA >5-15cm	Dent >5-15 cm	186,85	176,41	189,24	198,75	186,85	189,64	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	MOSSA 2-5cm	Dent 2-5 cm	107,7	99,5	109,51	120,78	107,7	109,82	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	PARTIDO	Broken	77,4	134,06	83,98	102,19	229,53	181,53	252,91	30,5	109,11	tb*
AVENTAL DA FTE	Front Bumper Skirt	RASPADO >5-15cm	Medium Scuffed >5-15cm	111,85	101,41	114,24	123,75	111,85	114,64	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	RASPADO 2-5cm	Light Scuffed 2-5cm	70,2	62	72,01	83,28	70,2	72,32	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	RISCO >15cm	Scratch >15 cm	111,85	101,41	114,24	123,75	111,85	114,64	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	RISCO >5-15cm	Scratch >5-15 cm	70,2	62	72,01	83,28	70,2	72,32	tb*	tb*	tb*	tb*
AVENTAL DA FTE	Front Bumper Skirt	RISCO 2-5cm	Scratch 2-5 cm	70,2	62	72,01	83,28	70,2	72,32	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	DISTORCIDO	Distorted	117,88	197,4	146,87	188,57	128,9	186,92	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	FALTA	Missing	117,88	197,4	146,87	188,57	128,9	186,92	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	MOSSA >15cm	Dent >15 cm	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	MOSSA >5-15cm	Dent >5-15 cm	186,85	181,99	189,52	186,85	186,85	189,64	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	MOSSA 2-5cm	Dent 2-5 cm	107,7	105,2	110,64	107,7	109,82	tb*	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	PARTIDO	Broken	117,88	197,4	146,87	188,57	128,9	186,92	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	RASPADO >5-15cm	Medium Scuffed >5-15cm	111,85	106,99	114,52	111,85	111,85	114,64	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	RASPADO 2-5cm	Light Scuffed 2-5cm	70,2	67,7	73,14	70,2	72,32	tb*	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	RISCO >15cm	Scratch >15 cm	111,85	106,99	114,52	111,85	111,85	114,64	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	RISCO >5-15cm	Scratch >5-15 cm	70,2	67,7	73,14	70,2	72,32	tb*	tb*	tb*	tb*	tb*
AVENTAL PÁRA-CHOQUES TRS	Rear Bumper Skirt	RISCO 2-5cm	Scratch 2-5 cm	70,2	67,7	73,14	70,2	72,32	tb*	tb*	tb*	tb*	tb*
BOTÃO VIDROS FRTE DTA	Front R. Window Control	FALTA	Missing	45,15	44,39	49,51	40,13	32,61	24,68	41,61	45,41	96,14	61,62
BOTÃO VIDROS FRTE DTA	Front R. Window Control	PARTIDO	Broken	45,15	44,39	49,51	40,13	32,61	24,68	41,61	45,41	96,14	61,62
BOTÃO VIDROS FRTE ESQ	Front L. Window Control	FALTA	Missing	68,23	94,15	143,95	130,74	155,64	81,85	73,93	62,95	120,21	76,84
BOTÃO VIDROS FRTE ESQ	Front L. Window Control	PARTIDO	Broken	68,23	94,15	143,95	130,74	155,64	81,85	73,93	62,95	120,21	76,84
BOTÃO VIDROS TRS DTO	Rear R. Window Control	FALTA	Missing	50,7	37,16	37,66	33,41	41,41	24,68	98,41	tb*	tb*	tb*
BOTÃO VIDROS TRS DTO	Rear R. Window Control	PARTIDO	Broken	50,7	37,16	37,66	33,41	41,41	24,68	98,41	tb*	tb*	tb*
BOTÃO VIDROS TRS ESQ	Rear L. Window Control	FALTA	Missing	50,7	37,16	45,49	33,47	41,41	24,68	98,41	tb*	tb*	tb*
BOTÃO VIDROS TRS ESQ	Rear L. Window Control	PARTIDO	Broken	50,7	37,16	45,49	33,47	41,41	24,68	98,41	tb*	tb*	tb*
BOTÕES MUDANÇAS	Gearshift Knob	FALTA	Missing	80,07	72,86	261,97	84,25	91,17	67,65	41,3	54,55	53,1	61,46
BOTÕES MUDANÇAS	Gearshift Knob	PARTIDO	Broken	80,07	72,86	261,97	84,25	91,17	67,65	41,3	54,55	53,1	61,46
BRAÇO LÍMPA-VIDROS FTE DTA	Front Right Wiper Arm	DISTORCIDO	Distorted	60,53	55,73	72,24	77,81	81,21	101,63	62,3	48,99	63,34	45,87
BRAÇO LÍMPA-VIDROS FTE DTA	Front Right Wiper Arm	FALTA	Missing	60,53	55,73	72,24	77,81	81,21	101,63	62,3	48,99	63,34	45,87
BRAÇO LÍMPA-VIDROS FTE DTA	Front Right Wiper Arm	PARTIDO	Broken	60,53	55,73	72,24	77,81	81,21	101,63	62,3	48,99	63,34	45,87
BRAÇO LÍMPA-VIDROS FTE ESQ	Front Left Wiper Arm	DISTORCIDO	Distorted	60,67	55,33	67,83	73,94	73,75	47,46	60,9	51,66	63,32	45,75
BRAÇO LÍMPA-VIDROS FTE ESQ	Front Left Wiper Arm	FALTA	Missing	60,67	55,33	67,83	73,94	73,75	47,46	60,9	51,66	63,32	45,75
BRAÇO LÍMPA-VIDROS FTE ESQ	Front Left Wiper Arm	PARTIDO	Broken	60,67	55,33	67,83	73,94	73,75	47,46	60,9	51,66	63,32	45,75
BRAÇO LÍMPA-VIDROS TRS	Rear Wiper Arm	DISTORCIDO	Distorted	41,73	43,42	46,82	50,71	64,22	27,01	34,31	29,21	tb*	tb*
BRAÇO LÍMPA-VIDROS TRS	Rear Wiper Arm	FALTA	Missing	41,73	43,42	46,82	50,71	64,22	27,01	34,31	29,21	tb*	tb*
BRAÇO LÍMPA-VIDROS TRS	Rear Wiper Arm	PARTIDO	Broken	41,73	43,42	46,82	50,71	64,22	27,01	34,31	29,21	tb*	tb*
CAPA DEPOSITO COMB. DTA	Right Fuel Cap	FALTA	Missing	30,89	34,07	30,17	49,69	26,04	82,01	42,17	27,34	24,63	12,93
CAPA DEPOSITO COMB. DTA	Right Fuel Cap	PARTIDO	Broken	30,89	34,07	30,17	49,69	26,04	82,01	42,17	27,34	24,63	12,93
CAPA DEPOSITO COMB. ESQ	Left Fuel Cap	FALTA	Missing	31,08	34,07	30,17	49,69	26,04	82,01	42,17	27,34	24,63	12,93
CAPA DEPOSITO COMB. ESQ	Left Fuel Cap	PARTIDO	Broken	31,08	34,07	30,17	49,69	26,04	82,01	42,17	27,34	24,63	12,93
CAPA ESPELHO DTA	Right Mirror Cap/Housing	DISTORCIDO	Distorted	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	FALTA	Missing	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	MOSSA >15cm	Dent >15 cm	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	MOSSA >5-15cm	Dent >5-15 cm	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	MOSSA 2-5cm	Dent 2-5 cm	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	PARTIDO	Broken	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	RASPADO >5-15cm	Medium Scuffed >5-15cm	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	RASPADO 2-5cm	Light Scuffed 2-5cm	63,62	80,23	126,56	102,5	77,13	101,08	87,51	56,62	55,22	54,76
CAPA ESPELHO DTA	Right Mirror Cap/Housing	RISCO >15cm	Scratch >15 cm	63,62	80,23	126,5							

DAMAGE AREA PT	DAMAGE AREA	SEVERITY DESCRIPTION PT	SEVERITY DESCRIPTION	Categoria Viatura / Vehicle Group						Categoria Viatura / Vehicle Group			
				MINI ECONOMY	COMPACT	FULL SIZE PREMIUM	INTERMEDIATE STANDARD	LUXURY	PASSENGER VAN	MEDIUM VAN	SMALL VAN	SPECIAL VAN	LARGE VAN
FECHO ADICIONAL TRS	Additional Lock (Rear)	FALTA	Missing	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	200	200	200	200
FECHO ADICIONAL TRS	Additional Lock (Rear)	PARTIDO	Broken	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	200	200	200	200
FECHO PORTA TRS DTA	Right Backdoor Lock	DISTORCIDO	Distorted	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	178,55	145,09	185,03	176,09
FECHO PORTA TRS DTA	Right Backdoor Lock	FALTA	Missing	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	178,55	145,09	185,03	176,09
FECHO PORTA TRS DTA	Right Backdoor Lock	PARTIDO	Broken	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	178,55	145,09	185,03	176,09
FECHO TAMPA MALA	Hatchback Lock	DISTORCIDO	Distorted	71,87	68,17	135,49	109,93	145,68	58,25	178,55	145,09	185,03	176,09
FECHO TAMPA MALA	Hatchback Lock	FALTA	Missing	71,87	68,17	135,49	109,93	145,68	58,25	178,55	145,09	185,03	176,09
FECHO TAMPA MALA	Hatchback Lock	PARTIDO	Broken	71,87	68,17	135,49	109,93	145,68	58,25	178,55	145,09	185,03	176,09
FORRO BANCO FTE DTO	Front R. Seat Base Cover	CORTADO	Cut	189,93	229,22	283,42	271,93	777,86	110	171,08	149,01	372,81	281,65
FORRO BANCO FTE DTO	Front R. Seat Base Cover	FALTA	Missing	189,93	229,22	283,42	271,93	777,86	110	171,08	149,01	372,81	281,65
FORRO BANCO FTE DTO	Front R. Seat Base Cover	QUEIMADO	Burnt	189,93	229,22	283,42	271,93	777,86	110	171,08	149,01	372,81	281,65
FORRO BANCO FTE DTD	Front L. Seat Base Cover	SUIJO	Soiled/Stained	185,88	236,19	282,35	243,62	672,66	113,75	212,62	166,43	173,83	207,67
FORRO BANCO FTE DTD	Front L. Seat Base Cover	CORTADO	Cut	185,88	236,19	282,35	243,62	672,66	113,75	212,62	166,43	173,83	207,67
FORRO BANCO FTE DTD	Front L. Seat Base Cover	FALTA	Missing	185,88	236,19	282,35	243,62	672,66	113,75	212,62	166,43	173,83	207,67
FORRO BANCO FTE DTD	Front L. Seat Base Cover	QUEIMADO	Burnt	185,88	236,19	282,35	243,62	672,66	113,75	212,62	166,43	173,83	207,67
FORRO BANCO FTE DTD	Front L. Seat Base Cover	SUIJO	Soiled/Stained	185,88	236,19	282,35	243,62	650,66	113,75	212,62	166,43	173,83	207,67
FORRO BANCO TRS DTO	Rear R. Seat Base Cover	CORTADO	Cut	22,5	251,82	192,05	329,53	500,12	131,32	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTO	Rear R. Seat Base Cover	FALTA	Missing	22,5	251,82	192,05	329,53	500,12	131,32	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTO	Rear R. Seat Base Cover	QUEIMADO	Burnt	22,5	251,82	192,05	329,53	500,12	131,32	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTO	Rear R. Seat Base Cover	SUIJO	Soiled/Stained	22,5	251,82	192,05	329,53	500,12	131,32	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTD	Rear L. Seat Base Cover	CORTADO	Cut	22,5	273,26	243,07	423,43	956,43	138,4	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTD	Rear L. Seat Base Cover	FALTA	Missing	22,5	273,26	243,07	423,43	956,43	138,4	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTD	Rear L. Seat Base Cover	QUEIMADO	Burnt	22,5	273,26	243,07	423,43	956,43	138,4	tbc*	tbc*	tbc*	tbc*
FORRO BANCO TRS DTD	Rear L. Seat Base Cover	SUIJO	Soiled/Stained	22,5	273,26	243,07	423,43	934,43	138,4	tbc*	tbc*	tbc*	tbc*
FORRO COSTAS BANCO FTE DTO	Front R. Seat Back Cover	CORTADO	Cut	259,35	289,07	361,98	346,2	630,65	200,79	147,89	206,58	356,26	235,35
FORRO COSTAS BANCO FTE DTO	Front R. Seat Back Cover	FALTA	Missing	259,35	289,07	361,98	346,2	630,65	200,79	147,89	206,58	356,26	235,35
FORRO COSTAS BANCO FTE DTO	Front R. Seat Back Cover	QUEIMADO	Burnt	259,35	289,07	361,98	346,2	630,65	200,79	147,89	206,58	356,26	235,35
FORRO COSTAS BANCO FTE DTD	Front L. Seat Back Cover	SUIJO	Soiled/Stained	259,35	289,07	361,98	346,2	630,65	200,79	147,89	206,58	356,26	235,35
FORRO COSTAS BANCO FTE DTD	Front L. Seat Back Cover	CORTADO	Cut	259,21	314,1	351,66	358,53	661,16	209,78	189,2	207,14	219,65	234,08
FORRO COSTAS BANCO FTE DTD	Front L. Seat Back Cover	FALTA	Missing	259,21	314,1	351,66	358,53	661,16	209,78	189,2	207,14	219,65	234,08
FORRO COSTAS BANCO FTE DTD	Front L. Seat Back Cover	QUEIMADO	Burnt	259,21	314,1	351,66	358,53	661,16	209,78	189,2	207,14	219,65	234,08
FORRO COSTAS BANCO FTE DTD	Front L. Seat Back Cover	SUIJO	Soiled/Stained	259,21	314,1	351,66	358,53	639,16	209,78	189,2	207,14	219,65	234,08
FORRO COSTAS BANCO TRS DTO	Rear R. Seat Back Cover	CORTADO	Cut	153,28	205,37	326,09	252,51	540,87	158,32	tbc*	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTO	Rear R. Seat Back Cover	FALTA	Missing	153,28	205,37	326,09	252,51	540,87	158,32	tbc*	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTO	Rear R. Seat Back Cover	QUEIMADO	Burnt	153,28	205,37	326,09	252,51	540,87	158,32	tbc*	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTD	Rear L. Seat Back Cover	SUIJO	Soiled/Stained	153,28	205,37	326,09	252,51	540,87	158,32	tbc*	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTD	Rear L. Seat Back Cover	CORTADO	Cut	183,22	233,66	430,67	260,77	539,89	162,26	178,5	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTD	Rear L. Seat Back Cover	FALTA	Missing	183,22	233,66	430,67	260,77	539,89	162,26	178,5	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTD	Rear L. Seat Back Cover	QUEIMADO	Burnt	183,22	233,66	430,67	260,77	539,89	162,26	178,5	tbc*	tbc*	tbc*
FORRO COSTAS BANCO TRS DTD	Rear L. Seat Back Cover	SUIJO	Soiled/Stained	183,22	233,66	430,67	260,77	539,89	162,26	178,5	tbc*	tbc*	tbc*
FORRO PISO	Fitted Carpet Whole	CORTADO	Cut	412,56	528,13	982,93	797,52	1299,24	570,94	731,62	373,65	480,71	390,77
FORRO PISO	Fitted Carpet Whole	FALTA	Missing	412,56	528,13	982,93	797,52	1299,24	570,94	731,62	373,65	480,71	390,77
FORRO PISO	Fitted Carpet Whole	QUEIMADO	Burnt	412,56	528,13	982,93	797,52	1299,24	570,94	731,62	373,65	480,71	390,77
FORRO PISO	Fitted Carpet Whole	SUIJO	Soiled/Stained	390,56	506,13	960,93	775,52	1277,24	548,94	709,62	351,65	458,71	390,77
FORRO TEJADILHO	Inner Roof Lining	CORTADO	Cut	396,74	530,89	796,77	747,71	769,38	849,61	533,46	358,02	369,7	863,1
FORRO TEJADILHO	Inner Roof Lining	QUEIMADO	Burnt	396,74	530,89	796,77	747,71	769,38	849,61	533,46	358,02	369,7	863,1
FORRO TEJADILHO	Inner Roof Lining	SUIJO	Soiled/Stained	396,74	530,89	796,77	747,71	769,38	849,61	533,46	358,02	369,7	863,1
FRISO DO PÁRA-CHOQUES FTE	Front Bumper Moulding	DISTORCIDO	Distorted	123,75	217,34	199,96	201,65	247,55	133,78	101,35	136,7	28,21	89,86
FRISO DO PÁRA-CHOQUES FTE	Front Bumper Moulding	FALTA	Missing	123,75	217,34	199,96	201,65	247,55	133,78	101,35	136,7	28,21	89,86
FRISO DO PÁRA-CHOQUES FTE	Front Bumper Moulding	PARTIDO	Broken	123,75	217,34	199,96	201,65	247,55	133,78	101,35	136,7	28,21	89,86
FRISO DO PÁRA-CHOQUES TRS	Rear Bumper Moulding	DISTORCIDO	Distorted	180,08	175,72	186,74	131,61	290,14	tbc*	249,16	111,69	tbc*	62,55
FRISO DO PÁRA-CHOQUES TRS	Rear Bumper Moulding	FALTA	Missing	180,08	175,72	186,74	131,61	290,14	tbc*	249,16	111,69	tbc*	62,55
FRISO DO PÁRA-CHOQUES TRS	Rear Bumper Moulding	PARTIDO	Broken	180,08	175,72	186,74	131,61	290,14	tbc*	249,16	111,69	tbc*	62,55
FRISO PORTA FTE DTA	Front Right Door Moulding	DISTORCIDO	Distorted	124,16	116,61	131,05	137,59	109,36	52,42	57,07	41,68	67,71	77,59
FRISO PORTA FTE DTA	Front Right Door Moulding	FALTA	Missing	124,16	116,61	131,05	137,59	109,36	52,42	57,07	41,68	67,71	77,59
FRISO PORTA FTE DTA	Front Right Door Moulding	PARTIDO	Broken	124,16	116,61	131,05	137,59	109,36	52,42	57,07	41,68	67,71	77,59
FRISO PORTA FTE DTD	Front Left Door Moulding	DISTORCIDO	Distorted	124,11	120,44	131,05	143,49	111,79	55,65	55,45	42,92	67,71	78,1
FRISO PORTA FTE DTD	Front Left Door Moulding	FALTA	Missing	124,11	120,44	131,05	143,49	111,79	55,65	55,45	42,92	67,71	78,1
FRISO PORTA FTE DTD	Front Left Door Moulding	PARTIDO	Broken	124,11	120,44	131,05	143,49	111,79	55,65	55,45	42,92	67,71	78,1
FRISO PORTA TRS DTA	Rear Right Door Gasket	DISTORCIDO	Distorted	68,06	62,69	121,85	76,87	132,02	112,99	142,11	55,66	7,5	66,79
FRISO PORTA TRS DTA	Rear Right Door Gasket	FALTA	Missing	68,06	62,69	121,85	76,87	132,02	112,99	142,11	55,66	7,5	66,79
FRISO PORTA TRS DTA	Rear Right Door Gasket	PARTIDO	Broken	68,06	62,69	121,85	76,87	132,02	112,99	142,11	55,66	7,5	66,79
FRISO PORTA TRS DTD	Rear Left Door Gasket	DISTORCIDO	Distorted	68,03	60,34	124,61	76,15	141,31	114,03	130,98	54,48	tbc*	tbc*
FRISO PORTA TRS DTD	Rear Left Door Gasket	FALTA	Missing	68,03	60,34	124,61	76,15	141,31	114,03	130,98	54,48	tbc*	tbc*
FRISO PORTA TRS DTD	Rear Left Door Gasket	PARTIDO	Broken	68,03	60,34	124,61	76,15	141,31	114,03	130,98	54,48	tbc*	tbc*
G.LAMAS FTE DTO	Right Front Side Wall	DISTORCIDO	Distorted	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	2003,03	tbc*	2406,12	3511,73
G.LAMAS FTE DTO	Right Front Side Wall	MOSSA >5-15cm	Dent >5-15 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	639,35	tbc*	1038,61	1044,05
G.LAMAS FTE DTO	Right Front Side Wall	MOSSA >5-15cm	Dent >5-15 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	465,72	tbc*	764,66	751,81
G.LAMAS FTE DTO	Right Front Side Wall	MOSSA 2-5cm	Dent 2-5 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	261,94	tbc*	427,1	418,42
G.LAMAS FTE DTO	Right Front Side Wall	PARTIDO	Broken	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	2003,03	tbc*	2406,12	3511,73
G.LAMAS FTE DTD	Right Front Side Wall	RASPADO >5-15cm	Medium Scuffed >5-15cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	390,72	tbc*	689,66	676,81
G.LAMAS FTE DTD	Right Front Side Wall	RASPADO 2-5cm	Light Scuffed 2-5cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	224,44	tbc*	389,6	380,92
G.LAMAS FTE DTD	Right Front Side Wall	RISCO >15cm	Scratch >15 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	526,85	tbc*	926,11	931,55
G.LAMAS FTE DTD	Right Front Side Wall	RISCO >5-15cm	Scratch >5-15 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	390,72	tbc*	689,66	676,81
G.LAMAS FTE DTD	Right Front Side Wall	RISCO 2-5cm	Scratch 2-5 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	224,44	tbc*	389,6	380,92
G.LAMAS FTE DTD	Right Front Side Wall	DISTORCIDO	Distorted	501,79	551,02	657,07	619,55	757,02	581,07	589,25	552,54	569,6	667,37
G.LAMAS FTE DTD	Right Front Side Wall	FALTA	Missing	501,79	551,02	657,07	619,55	757,02	581,07	589,25	552,54	569,6	667,37
G													

Custos Admin. Danos / Administration Fee 36,90 (IVA incluido/VAT Included)				Categoria Viatura / Vehicle Group					Categoria Viatura / Vehicle Group				
DAMAGE AREA PT	DAMAGE AREA	SEVERITY DESCRIPTION PT	SEVERITY DESCRIPTION	MINI ECONOMY	COMPACT	FULL SIZE PREMIUM	INTERMEDIATE STANDARD	LUXURY	PASSENGER VAN	MEDIUM VAN	SMALL VAN	SPECIAL VAN	LARGE VAN
G.LAMAS TRS ESQ	Rear Left Wing	FALTA	Missing	1365,43	1650,35	1825,11	1743,63	2715,28	1928,69	2088,36	1575,09	1596,82	2015,51
G.LAMAS TRS ESQ	Rear Left Wing	MOSSA >15cm	Dent >15 cm	397,83	441,93	440,11	443,08	688,46	450	802,36	541,05	716,64	744,18
G.LAMAS TRS ESQ	Rear Left Wing	MOSSA >5-15cm	Dent >5-15 cm	270,03	300,06	300,74	303,61	483,31	307,29	559,59	374,16	508,57	517,51
G.LAMAS TRS ESQ	Rear Left Wing	MOSSA 2-5cm	Dent 2-5 cm	135,99	153,75	151,98	154,57	250,05	153,33	291,86	193,73	268,84	269,22
G.LAMAS TRS ESQ	Rear Left Wing	PARTIDO	Broken	1365,43	1650,35	1825,11	1743,63	2715,28	1928,69	2088,36	1575,09	1596,82	2015,51
G.LAMAS TRS ESQ	Rear Left Wing	RASPADO >5-15cm	Medium Scuffed >5-15cm	195,03	225,06	225,74	228,61	408,31	232,29	484,59	299,16	433,57	442,51
G.LAMAS TRS ESQ	Rear Left Wing	RASPADO 2-5cm	Light Scuffed 2-5cm	98,49	116,25	114,48	117,07	212,55	115,83	254,36	156,23	231,34	231,72
G.LAMAS TRS ESQ	Rear Left Wing	RISCO >15cm	Scratch >15 cm	285,33	329,43	327,61	330,58	575,96	337,61	689,86	428,55	604,14	631,68
G.LAMAS TRS ESQ	Rear Left Wing	RISCO >5-15cm	Scratch >5-15 cm	195,03	225,06	225,74	228,61	408,31	232,29	484,59	299,16	433,57	442,51
G.LAMAS TRS ESQ	Rear Left Wing	RISCO 2-5cm	Scratch 2-5 cm	98,49	116,25	114,48	117,07	212,55	115,83	254,36	156,23	231,34	231,72
GRELHA FTE	Front Grille	DISTORCIDO	Distorted	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	FALTA	Missing	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	MOSSA >15cm	Dent >15 cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	MOSSA >5-15cm	Dent >5-15 cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	MOSSA 2-5cm	Dent 2-5 cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	PARTIDO	Broken	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	RASPADO >5-15cm	Medium Scuffed >5-15cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	RASPADO 2-5cm	Light Scuffed 2-5cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	RISCO >15cm	Scratch >15 cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	RISCO >5-15cm	Scratch >5-15 cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA FTE	Front Grille	RISCO 2-5cm	Scratch 2-5 cm	151,69	165,45	165,33	248,36	170,66	242,98	259,5	173,13	201,98	235,26
GRELHA INFERIOR PÁRA-CHOQUES	Lower Front Bumper Grill	DISTORCIDO	Distorted	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*
GRELHA INFERIOR PÁRA-CHOQUES	Lower Front Bumper Grill	FALTA	Missing	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*
GRELHA INFERIOR PÁRA-CHOQUES	Lower Front Bumper Grill	PARTIDO	Broken	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*
INTERRUPTOR LUZ	Lights Switch	FALTA	Missing	tbc*	32,83	85,32	65,62	282,56	tbc*	tbc*	tbc*	tbc*	183,45
INTERRUPTOR LUZ	Lights Switch	PARTIDO	Broken	tbc*	32,83	85,32	65,62	282,56	tbc*	tbc*	tbc*	tbc*	183,45
ISQUEIRO	Lighter	FALTA	Missing	28,63	26,98	20,34	28,34	30,29	35,76	31,46	20,74	11,45	29,76
ISQUEIRO	Lighter	PARTIDO	Broken	28,63	26,98	20,34	28,34	30,29	35,76	31,46	20,74	11,45	29,76
JANTE FTE DTA ALUMINIO	Front R. Wheel Rim Alloy	DISTORCIDO	Distorted	203,86	283,7	520,15	293,08	298,49	208,09	141,1	151,15	233,8	146,75
JANTE FTE DTA ALUMINIO	Front R. Wheel Rim Alloy	FALTA	Missing	203,86	283,7	520,15	293,08	298,49	208,09	141,1	151,15	233,8	146,75
JANTE FTE DTA ALUMINIO	Front R. Wheel Rim Alloy	PARTIDO	Broken	203,86	283,7	520,15	293,08	298,49	208,09	141,1	151,15	233,8	146,75
JANTE FTE DTA ALUMINIO	Front R. Wheel Rim Alloy	RASPADO >5-15cm	Medium Scuffed >5-15cm	80	80	80	80	80	80	80	80	80	80
JANTE FTE DTA ALUMINIO	Front R. Wheel Rim Alloy	RASPADO 2-5cm	Light Scuffed 2-5cm	60	60	60	60	60	60	60	60	60	60
JANTE FTE DTA ALUMINIO	Front R. Wheel Rim Alloy	DISTORCIDO	Distorted	203,86	283,7	520,15	293,08	298,49	208,09	141,1	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	293,08	298,49	208,09	141,1	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	293,08	298,49	208,09	141,1	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	76,52	77,15	79,44	77,9	84,27	75,82	70,92	71,02	92,56	74,32
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	68,27	68,9	70,78	69,77	77,18	67,39	65,62	64,98	84,22	69,84
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	80	80	80	80	80	80	80	80	80	80
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	60	60	60	60	60	60	60	60	60	60
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	76,52	77,15	79,44	77,9	84,27	75,82	70,92	71,02	92,56	74,32
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	68,27	68,9	70,78	69,77	77,18	67,39	65,62	64,98	84,22	69,84
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	80	80	80	80	80	80	80	80	80	80
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	60	60	60	60	60	60	60	60	60	60
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	76,52	77,15	79,44	77,9	84,27	75,82	70,92	71,02	92,56	74,32
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	68,27	68,9	70,78	69,77	77,18	67,39	65,62	64,98	84,22	69,84
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	80	80	80	80	80	80	80	80	80	80
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	60	60	60	60	60	60	60	60	60	60
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	76,52	77,15	79,44	77,9	84,27	75,82	70,92	71,02	92,56	74,32
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	68,27	68,9	70,78	69,77	77,18	67,39	65,62	64,98	84,22	69,84
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	PARTIDO	Broken	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO >5-15cm	Medium Scuffed >5-15cm	80	80	80	80	80	80	80	80	80	80
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	RASPADO 2-5cm	Light Scuffed 2-5cm	60	60	60	60	60	60	60	60	60	60
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	DISTORCIDO	Distorted	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,75
JANTE FTE DTA FERRO	Front R. Wheel Rim Iron	FALTA	Missing	203,86	283,7	520,15	300,98	298,49	208,09	141,2	151,15	233,8	146,

DAMAGE AREA PT	DAMAGE AREA	SEVERITY DESCRIPTION PT	SEVERITY DESCRIPTION	Categoria Viatura / Vehicle Group						Categoria Viatura / Vehicle Group			
				MINI ECONOMY	COMPACT	FULL SIZE PREMIUM	INTERMEDIATE STANDARD	LUXURY	PASSENGER VAN	MEDIUM VAN	SMALL VAN	SPECIAL VAN	LARGE VAN
PORTA CORRER	Right Sliding Door	MOSSA >15cm	Dent >15 cm	tbc*	505,67	516,93	507,54	646,11	tbc*	625,9	520,5	789,2	740,52
PORTA CORRER	Right Sliding Door	MOSSA >15cm	Dent >15 cm	tbc*	347,81	364,15	365,34	436,94	tbc*	426,07	354,67	549,64	515,14
PORTA CORRER	Right Sliding Door	MOSSA 2-5cm	Dent 2-5 cm	tbc*	178,19	193,56	204,38	208,47	tbc*	210,04	177,06	276,98	267,44
PORTA CORRER	Right Sliding Door	PARTIDO	Broken	tbc*	1252,85	1568,68	1546,75	1681,78	tbc*	1498,48	1013,29	1772	1712,54
PORTA CORRER	Right Sliding Door	RASPADO >15cm	Medium Scuffed >5-15cm	tbc*	272,81	289,15	290,34	361,94	tbc*	351,07	279,67	474,64	440,14
PORTA CORRER	Right Sliding Door	RASPADO 2-5cm	Light Scuffed 2-5cm	tbc*	140,69	156,06	166,88	170,97	tbc*	172,54	139,56	239,48	229,94
PORTA CORRER	Right Sliding Door	RISCO >15cm	Scratch >15 cm	tbc*	393,17	404,43	395,04	533,61	tbc*	513,4	408	676,7	628,02
PORTA CORRER	Right Sliding Door	RISCO >5-15cm	Scratch >5-15 cm	tbc*	272,81	289,15	290,34	361,94	tbc*	351,07	279,67	474,64	440,14
PORTA CORRER	Right Sliding Door	RISCO 2-5cm	Scratch 2-5 cm	tbc*	140,69	156,06	166,88	170,97	tbc*	172,54	139,56	239,48	229,94
PORTA CORRER ESQ	Left Sliding Door	DISTORCIDO	Distorted	tbc*	1307,98	1568,68	tbc*	tbc*	tbc*	tbc*	1029,7	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	MOSSA >15cm	Dent >15 cm	tbc*	505,67	516,93	tbc*	tbc*	tbc*	tbc*	490,5	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	MOSSA >5-15cm	Dent >5-15 cm	tbc*	347,81	364,15	tbc*	tbc*	tbc*	tbc*	331,47	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	MOSSA 2-5cm	Dent 2-5 cm	tbc*	178,19	193,56	tbc*	tbc*	tbc*	tbc*	162,57	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	PARTIDO	Broken	tbc*	1307,98	1568,68	tbc*	tbc*	tbc*	tbc*	1029,7	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	RASPADO >15cm	Medium Scuffed >5-15cm	tbc*	272,81	289,15	tbc*	tbc*	tbc*	tbc*	256,47	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	RASPADO 2-5cm	Light Scuffed 2-5cm	tbc*	140,69	156,06	tbc*	tbc*	tbc*	tbc*	125,07	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	RISCO >15cm	Scratch >15 cm	tbc*	393,17	404,43	tbc*	tbc*	tbc*	tbc*	378	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	RISCO >5-15cm	Scratch >5-15 cm	tbc*	272,81	289,15	tbc*	tbc*	tbc*	tbc*	256,47	tbc*	tbc*
PORTA CORRER ESQ	Left Sliding Door	RISCO 2-5cm	Scratch 2-5 cm	tbc*	140,69	156,06	tbc*	tbc*	tbc*	tbc*	125,07	tbc*	tbc*
PORTA FTE DTA	Front Right Door	DISTORCIDO	Distorted	968,05	1036,94	1269,88	1153,17	1348,05	1050,56	1211,1	1094,56	1357,54	1346,09
PORTA FTE DTA	Front Right Door	MOSSA >15cm	Dent >15 cm	462,82	488,99	503,34	485,77	553,94	508,11	573,29	511,33	535,56	558,21
PORTA FTE DTA	Front Right Door	MOSSA >5-15cm	Dent >5-15 cm	322,58	340,33	352,16	338,97	376,54	354,94	383,16	352,04	367,48	372,5
PORTA FTE DTA	Front Right Door	MOSSA 2-5cm	Dent 2-5 cm	171,13	179,1	185,78	178,61	184,54	184,07	180,69	180,48	185,2	176,83
PORTA FTE DTA	Front Right Door	PARTIDO	Broken	968,05	1036,94	1269,88	1153,17	1348,05	1050,56	1211,1	1094,56	1357,54	1346,09
PORTA FTE DTA	Front Right Door	RASPADO >15cm	Medium Scuffed >5-15cm	247,58	265,33	277,16	263,97	301,54	279,94	308,16	277,04	292,48	297,5
PORTA FTE DTA	Front Right Door	RASPADO 2-5cm	Light Scuffed 2-5cm	133,63	141,6	148,28	141,11	147,04	146,57	143,19	142,98	148,02	139,33
PORTA FTE DTA	Front Right Door	RISCO >15cm	Scratch >15 cm	350,32	376,49	390,84	373,27	441,44	395,61	460,79	398,83	423,06	445,71
PORTA FTE DTA	Front Right Door	RISCO >5-15cm	Scratch >5-15 cm	247,58	265,33	277,16	263,97	301,54	279,94	308,16	277,04	292,48	297,5
PORTA FTE DTA	Front Right Door	RISCO 2-5cm	Scratch 2-5 cm	133,63	141,6	148,28	141,11	147,04	146,57	143,19	142,98	148,02	139,33
PORTA FTE ESQ	Front Left Door	DISTORCIDO	Distorted	962,69	1027,68	1274,62	1115,61	1350,78	1050,56	1194,13	1102,15	1361,46	1349,37
PORTA FTE ESQ	Front Left Door	MOSSA >15cm	Dent >15 cm	462,49	488,99	503,34	486,59	553,94	508,11	577,28	511,33	535,56	558,21
PORTA FTE ESQ	Front Left Door	MOSSA >5-15cm	Dent >5-15 cm	322,38	340,33	352,16	338,98	376,54	354,94	384,75	352,04	367,48	372,5
PORTA FTE ESQ	Front Left Door	MOSSA 2-5cm	Dent 2-5 cm	177,08	179,1	185,78	177,94	184,54	184,07	180,1	180,48	185,2	176,83
PORTA FTE ESQ	Front Left Door	PARTIDO	Broken	962,69	1027,68	1274,62	1115,61	1350,78	1050,56	1194,13	1102,15	1361,46	1349,37
PORTA FTE ESQ	Front Left Door	RASPADO >15cm	Medium Scuffed >5-15cm	247,38	265,33	277,16	263,98	301,54	279,94	309,75	277,04	292,48	297,5
PORTA FTE ESQ	Front Left Door	RASPADO 2-5cm	Light Scuffed 2-5cm	133,58	141,6	148,28	140,44	147,04	146,57	142,6	142,98	148,02	139,33
PORTA FTE ESQ	Front Left Door	RISCO >15cm	Scratch >15 cm	349,99	376,49	390,84	374,09	441,44	395,61	464,78	398,83	423,06	445,71
PORTA FTE ESQ	Front Left Door	RISCO >5-15cm	Scratch >5-15 cm	247,38	265,33	277,16	263,98	301,54	279,94	309,75	277,04	292,48	297,5
PORTA FTE ESQ	Front Left Door	RISCO 2-5cm	Scratch 2-5 cm	133,58	141,6	148,28	140,44	147,04	146,57	142,6	142,98	148,02	139,33
PORTA LUVAS	Gloves Compartment (Door)	FALTA	Missing	151,5	258,23	217,78	219,58	261,17	292,33	257,27	169,5	238,88	108,84
PORTA LUVAS	Gloves Compartment (Door)	PARTIDO	Broken	151,5	258,23	217,78	219,58	261,17	292,33	257,27	169,5	238,88	108,84
PORTA TRS DTO	Rear Right Door	DISTORCIDO	Distorted	897,65	968,46	1158,24	1124,55	1425,65	981,1	1248,47	1056,05	1721,19	tbc*
PORTA TRS DTO	Rear Right Door	MOSSA >15cm	Dent >15 cm	433,33	464,31	470,22	461,21	480,93	504,5	480,61	426,21	451,38	tbc*
PORTA TRS DTO	Rear Right Door	MOSSA >5-15cm	Dent >5-15 cm	299,31	320,47	324,91	318,43	331,03	351,88	327,79	294,85	308,42	tbc*
PORTA TRS DTO	Rear Right Door	MOSSA 2-5cm	Dent 2-5 cm	156,46	165,93	167,81	164,44	169,33	182,22	162,69	154,76	159,56	tbc*
PORTA TRS DTO	Rear Right Door	PARTIDO	Broken	897,65	968,46	1158,24	1124,55	1425,65	981,1	1248,47	1056,05	1721,19	tbc*
PORTA TRS DTO	Rear Right Door	RASPADO >15cm	Medium Scuffed >5-15cm	224,31	245,47	249,91	243,43	256,03	276,88	252,79	219,85	232,06	tbc*
PORTA TRS DTO	Rear Right Door	RASPADO 2-5cm	Light Scuffed 2-5cm	118,96	128,43	130,31	126,94	131,83	144,72	125,19	117,26	122,06	tbc*
PORTA TRS DTO	Rear Right Door	RISCO >15cm	Scratch >15 cm	320,83	351,81	357,72	348,71	368,43	392	368,11	313,71	338,88	tbc*
PORTA TRS DTO	Rear Right Door	RISCO >5-15cm	Scratch >5-15 cm	224,31	245,47	249,91	243,43	256,03	276,88	252,79	219,85	232,06	tbc*
PORTA TRS DTO	Rear Right Door	RISCO 2-5cm	Scratch 2-5 cm	118,96	128,43	130,31	126,94	131,83	144,72	125,19	117,26	122,06	tbc*
PORTA TRS ESQ	Rear Left Door	DISTORCIDO	Distorted	886,73	981,32	1159,69	1118,26	1425,43	1248,47	1113,82	1248,47	1056,05	1721,19
PORTA TRS ESQ	Rear Left Door	MOSSA >15cm	Dent >15 cm	433,09	464,31	470,22	460,33	480,93	504,5	480,61	426,21	451,38	tbc*
PORTA TRS ESQ	Rear Left Door	MOSSA >5-15cm	Dent >5-15 cm	299,19	320,47	324,91	317,74	331,03	351,88	327,79	294,85	308,42	tbc*
PORTA TRS ESQ	Rear Left Door	MOSSA 2-5cm	Dent 2-5 cm	156,45	165,93	167,81	164,01	169,33	182,22	162,69	154,76	159,56	tbc*
PORTA TRS ESQ	Rear Left Door	PARTIDO	Broken	886,73	981,32	1159,69	1118,26	1425,43	1248,47	1113,82	1248,47	1056,05	1721,19
PORTA TRS ESQ	Rear Left Door	RASPADO >15cm	Medium Scuffed >5-15cm	224,19	245,47	249,91	242,74	256,03	276,88	252,79	219,85	232,06	tbc*
PORTA TRS ESQ	Rear Left Door	RASPADO 2-5cm	Light Scuffed 2-5cm	118,95	128,43	130,31	126,94	131,83	144,72	125,19	117,26	122,06	tbc*
PORTA TRS ESQ	Rear Left Door	RISCO >15cm	Scratch >15 cm	320,59	351,81	357,72	347,83	368,43	392	368,11	313,71	338,88	tbc*
PORTA TRS ESQ	Rear Left Door	RISCO >5-15cm	Scratch >5-15 cm	224,19	245,47	249,91	242,74	256,03	276,88	252,79	219,85	232,06	tbc*
PORTA TRS ESQ	Rear Left Door	RISCO 2-5cm	Scratch 2-5 cm	118,95	128,43	130,31	126,94	131,83	144,72	125,19	117,26	122,06	tbc*
PROTECCAO INFERIOR	Underside Protection	DISTORCIDO	Distorted	96,49	113,85	251,44	168,43	569,3	77,31	165,5	43,5	58,48	216,22
PROTECCAO INFERIOR	Underside Protection	FALTA	Missing	96,49	113,85	251,44	168,43	569,3	77,31	165,5	43,5	58,48	216,22
PROTECCAO INFERIOR	Underside Protection	PARTIDO	Broken	96,49	113,85	251,44	168,43	569,3	77,31	165,5	43,5	58,48	216,22
RADIO	Radio	FALTA	Missing	515,7	559,13	987,97	461,78	882,26	367,58	242,59	545,25	309,74	319,83
RADIO	Radio	PARTIDO	Broken	515,7	559,13	987,97	461,78	882,26	367,58	242,59	545,25	309,74	319,83
REDE SEPARADORA	Boot Net	FALTA	Missing	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*
REDE SEPARADORA	Boot Net	PARTIDO	Broken	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*
Right Side Damage TBA HQ	Right Side Damage TBA HQ	PERITAGEM	To Be Expertised HQ	0,001	0,001	0,001	0,001	0,001	0,001	0,001	0,001	0,001	0,001
SPLILER PARA-CHOQUES TRS	Rear Bumper Spoiler	DISTORCIDO	Distorted	117,88	197,4	146,87	188,57	128,9	186,92	tbc*	tbc*	tbc*	tbc*
SPLILER PARA-CHOQUES TRS	Rear Bumper Spoiler	FALTA	Missing	117,88	197,4	146,87	188,57	128,9	186,92	tbc*	tbc*	tbc*	tbc*
SPLILER PARA-CHOQUES TRS	Rear Bumper Spoiler	MOSSA >15cm	Dent >15 cm	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*	tbc*
SPLILER PARA-CHOQUES TRS	Rear Bumper Spoiler	MOSSA >5-15cm	Dent >5-15 cm	186,85	181,99	189,52	186,85	186,85	189,64	tbc*	tbc*	tbc*	tbc*
SPLILER PARA-CHOQUES TRS	Rear Bumper Spoiler	MOSSA 2-5cm	Dent 2-5 cm	107,7	105,2	110,64	107,7	109,82	tbc*	tbc*	tbc*	tbc*	tbc*
SPLILER PARA-CHOQUES TRS													

DAMAGE AREA PT	DAMAGE AREA	SEVERITY DESCRIPTION PT	SEVERITY DESCRIPTION	Categoria Viatura / Vehicle Group						Categoria Viatura / Vehicle Group			
				MINI ECONOMY	COMPACT	FULL SIZE PREMIUM	INTERMEDIATE STANDARD	LUXURY	PASSENGER VAN	MEDIUM VAN	SMALL VAN	SPECIAL VAN	LARGE VAN
TAPETES TRS	Fitted Carpet Rear	QUEIMADO	Burnt	tbct*	322,12	566,99	486,9	689,71	199,6	385,46	tbct*	201,05	tbct*
TAPETES TRS	Fitted Carpet Rear	SUJO	Soiled/Stained	tbct*	322,12	544,99	464,9	667,71	199,6	385,46	tbct*	201,05	tbct*
TECTO DE ABRIR	Sun Roof	DISTORCIDO	Distorted	998,51	2148,89	tbct*	633,71	4978,66	tbct*	tbct*	tbct*	tbct*	tbct*
TECTO DE ABRIR	Sun Roof	PARTIDO	Broken	998,51	2148,89	tbct*	633,71	4978,66	tbct*	tbct*	tbct*	tbct*	tbct*
TEJADILHO	Roof	DISTORCIDO	Distorted	1467,75	1909	2293,94	2095,85	2568,6	1825,59	2045,03	1881,47	1420,22	1901,78
TEJADILHO	Roof	MOSSA >15cm	Dent >15 cm	435,63	481,07	540,44	448,5	592,65	603,58	404,46	489,24	354,55	379,86
TEJADILHO	Roof	MOSSA >5-15cm	Dent >5-15 cm	346,48	384,21	433,65	358,22	472,68	487,37	315,17	384,4	280,86	296,46
TEJADILHO	Roof	MOSSA 2-5cm	Dent 2-5 cm	236,94	261,97	293,33	244,09	313,87	325,56	208,86	255,91	192,5	201,77
TEJADILHO	Roof	PARTIDO	Broken	1467,75	1909	2293,94	2095,85	2568,6	1825,59	2045,03	1881,47	1420,22	1901,78
TEJADILHO	Roof	RASPADO >5-15cm	Medium Scuffed >5-15cm	271,48	309,21	358,65	283,22	397,68	412,37	240,17	309,4	205,86	221,46
TEJADILHO	Roof	RASPADO 2-5cm	Light Scuffed 2-5cm	199,44	224,47	255,83	206,59	276,37	288,06	171,36	218,41	155	164,27
TEJADILHO	Roof	RISCO >15cm	Scratch >15 cm	323,13	368,57	427,94	336	480,15	491,08	291,96	376,74	242,05	267,36
TEJADILHO	Roof	RISCO >5-15cm	Scratch >5-15 cm	271,48	309,21	358,65	283,22	397,68	412,37	240,17	309,4	205,86	221,46
TEJADILHO	Roof	RISCO 2-5cm	Scratch 2-5 cm	199,44	224,47	255,83	206,59	276,37	288,06	171,36	218,41	155	164,27
TETO	Ceiling	CORTADO	Cut	396,74	530,89	796,77	747,71	769,38	849,61	533,46	358,02	369,7	863,1
TETO	Ceiling	QUEIMADO	Burnt	396,74	530,89	796,77	747,71	769,38	849,61	533,46	358,02	369,7	863,1
TETO	Ceiling	SUJO	Soiled/Stained	396,74	530,89	774,77	725,71	747,38	827,61	533,46	358,02	347,7	819,1
TOUCHSCREEN / COCKPIT	Touchscreen / Cockpit	PARTIDO	Broken	tbct*	tbct*	tbct*	1267,03	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
TRASEIRA ESQ TRK	Rear Angular Left (Vans)	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	2765,35	tbct*	1247,01	1449,2
TRASEIRA ESQ TRK	Rear Angular Left (Vans)	FALTA	Missing	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	2765,35	tbct*	1247,01	1449,2
TRASEIRA ESQ TRK	Rear Angular Left (Vans)	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	2765,35	tbct*	1247,01	1449,2
TRASEIRA ESQ TRK	Rear Angular Left (Vans)	RASPADO >5-15cm	Medium Scuffed >5-15cm	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	195,46	tbct*	205,16	207,5
TRASEIRA ESQ TRK	Rear Angular Left (Vans)	RASPADO 2-5cm	Light Scuffed 2-5cm	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	60,31	tbct*	89,99	80,42
TRIANGULO	Triangle	FALTA	Missing	30,36	26,7	34,59	31,33	39,85	tbct*	18,23	4,64	tbct*	23,83
TRIANGULO	Triangle	PARTIDO	Broken	30,36	26,7	34,59	31,33	39,85	tbct*	18,23	4,64	tbct*	23,83
TROCA COMBUSTIVEL	Wrong Refueling	TROCA COMBUSTIVEL	Incorrect Refuelling	300	300	300	300	300	300	300	300	300	300
TRSEIRA DTO TRK	Rear Angular Right (Vans)	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	1891,58	tbct*	1247,01	1447,68
TRSEIRA DTO TRK	Rear Angular Right (Vans)	FALTA	Missing	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	1891,58	tbct*	1247,01	1447,68
TRSEIRA DTO TRK	Rear Angular Right (Vans)	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	1891,58	tbct*	1247,01	1447,68
TRSEIRA DTO TRK	Rear Angular Right (Vans)	RASPADO >5-15cm	Medium Scuffed >5-15cm	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	184,44	tbct*	205,16	207,5
TRSEIRA DTO TRK	Rear Angular Right (Vans)	RASPADO 2-5cm	Light Scuffed 2-5cm	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	66,55	tbct*	89,99	80,42
UNIDADE CONTROLO AC	A/C Control Unit	FALTA	Missing	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
UNIDADE CONTROLO AC	A/C Control Unit	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO CORRER DTO	Right Sliding Door Glass	DISTORCIDO	Distorted	216,09	200,29	329,63	226,03	424,83	413,16	tbct*	tbct*	tbct*	tbct*
VIDRO CORRER DTO	Right Sliding Door Glass	PARTIDO	Broken	216,09	200,29	329,63	226,03	424,83	413,16	tbct*	tbct*	tbct*	tbct*
VIDRO CORRER ESQ	Left Sliding Door Glass	DISTORCIDO	Distorted	187,62	194,13	318,66	220,82	424,83	413,16	tbct*	tbct*	tbct*	tbct*
VIDRO CORRER ESQ	Left Sliding Door Glass	PARTIDO	Broken	187,62	194,13	318,66	220,82	424,83	413,16	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO DTO	Right SideWall Fix. Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO DTO	Right SideWall Fix. Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO DTO	Left SideWall Fix. Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO DTO	Left SideWall Fix. Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO DTO	Front Right Fixed Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO DTO	Front Right Fixed Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO FTE DTO	Front Left Fixed Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO FTE DTO	Front Left Fixed Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO FTE ESQ	Rear Right Fixed Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO FTE ESQ	Rear Right Fixed Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO TRS DTO.	Rear Left Fixed Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO TRS DTO.	Rear Left Fixed Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
VIDRO FIXO TRS ESQ.	Front Right Window	DISTORCIDO	Distorted	119,81	115,21	177,5	144,89	147,71	156,53	108,92	107,73	135,51	174,46
VIDRO FIXO TRS ESQ.	Front Right Window	PARTIDO	Broken	119,81	115,21	177,5	144,89	147,71	156,53	108,92	107,73	135,51	174,46
VIDRO PORTA FTE DTA	Front Left Window	DISTORCIDO	Distorted	118,41	112,5	154,04	140,14	146,5	156,53	112,83	105,52	135,51	174,46
VIDRO PORTA FTE DTA	Front Left Window	PARTIDO	Broken	118,41	112,5	154,04	140,14	146,5	156,53	112,83	105,52	135,51	174,46
VIDRO PORTA TRS DTO	Rear Right Backdoor Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	242,04	176,23	164,52	tbct*
VIDRO PORTA TRS DTO	Rear Right Backdoor Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	242,04	176,23	164,52	tbct*
VIDRO PORTA TRS DTO	Rear Right Door Window	DISTORCIDO	Distorted	113,71	108,95	182,26	167,88	241,22	253,42	242,04	176,23	164,52	tbct*
VIDRO PORTA TRS DTO	Rear Right Door Window	PARTIDO	Broken	113,71	108,95	182,26	167,88	241,22	253,42	242,04	176,23	164,52	tbct*
VIDRO PORTA TRS ESQ	Rear Left Backdoor Glass	DISTORCIDO	Distorted	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	249,54	176,23	164,52	tbct*
VIDRO PORTA TRS ESQ	Rear Left Backdoor Glass	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	249,54	176,23	164,52	tbct*
VIDRO PORTA TRS ESQ	Rear Left Door Window	DISTORCIDO	Distorted	112,31	112,73	185,14	122,36	270,46	253,42	249,54	176,23	164,52	tbct*
VIDRO PORTA TRS ESQ	Rear Left Door Window	PARTIDO	Broken	112,31	112,73	185,14	122,36	270,46	253,42	249,54	176,23	164,52	tbct*
VOLANTE	Steering Wheel	FALTA	Missing	346,85	467,81	457,09	500,58	695,27	230,19	322,52	300,75	189,48	183,64
VOLANTE	Steering Wheel	PARTIDO	Broken	346,85	467,81	457,09	500,58	695,27	230,19	322,52	300,75	189,48	183,64
(blank)	Front Left Speaker	FALTA	Missing	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
(blank)	Front Left Speaker	PARTIDO	Broken	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
(blank)	Spare Tyre Alloy Rim	FALTA	Missing	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*	tbct*
G.LAMAS FTE DTA	Front Right Wing	DISTORCIDO	Distorted	512,52	551,27	655,55	607,94	757,02	581,07	588,63	552,45	569,6	666,93
G.LAMAS FTE DTA	Front Right Wing	FALTA	Missing	512,52	551,27	655,55	607,94	757,02	581,07	588,63	552,45	569,6	666,93
G.LAMAS FTE DTA	Front Right Wing	MOSSA >15cm	Dent >15 cm	372,82	388,29	406,13	387,82	468,36	404,91	469,75	407,31	433,93	476,49
G.LAMAS FTE DTA	Front Right Wing	MOSSA >5-15cm	Dent >5-15 cm	253,1	263,12	273,03	260,48	307,72	270,5	303,54	268,11	286,9	308,48
G.LAMAS FTE DTA	Front Right Wing	MOSSA 2-5cm	Dent 2-5 cm	120,35	122,86	133,76	126,36	140,29	129,26	123,74	124,47	135,26	136,11
G.LAMAS FTE DTA	Front Right Wing	PARTIDO	Broken	512,52	551,27	655,55	607,94	757,02	581,07	588,63	552,45	569,6	666,93
G.LAMAS FTE DTA	Front Right Wing	RASPADO >5-15cm	Medium Scuffed >5-15cm	178,1	188,12	198,03	185,48	232,72	195,5	228,54	193,11	211,9	233,48
G.LAMAS FTE DTA	Front Right Wing	RASPADO 2-5cm	Light Scuffed 2-5cm	82,85	85,36	96,26	88,86	102,79	91,76	86,24	86,97	97,76	98,61
G.LAMAS FTE DTA	Front Right Wing	RISCO >15cm	Scratch >15 cm	260,32	275,79	293,63	275,32	355,86	292,41	357,25	294,81	321,43	363,99
G.LAMAS FTE DTA	Front Right Wing	RISCO >5-15cm	Scratch >5-15 cm	178,1	188,12	198,03	185,48	232,72	195,5	228,54	193,11	211,9	233,48
G.LAMAS FTE DTA	Front Right Wing	RISCO 2-5cm	Scratch 2-5 cm	82,85	85,36	96,26	88,86	102,79	91,76	86,24	86,97	97,76	98,61

Veículos eléctricos/ Electric vehicles		IVA Incluido / VAT included
A viatura deverá ser entregue com pelo menos 25% de bateria carregada. Caso contrário, será aplicado um Suplemento de Carregamento no valor de 50€	The vehicle must be delivered with at least 25% charged battery. Otherwise, a € 50 Charge Supplement will be applied	50,00 €
Extravio Cartão carregamento	Lost Charger Card	50,00 €
Extravio Cabo carregamento doméstico	Lost Domestic Charger	450,00 €
Extravio Cabo carregamento	Lost Normal Charger	400,00 €